



	Site Details	Customer / Agent Details			Registered Business Details		
Name	Asquith House & Austin Hall	Name	Tuscola (109) Ltd	Name		Kimpton Energy Solutions	
Address	Servia Road	Address	c/o Tuscola 109 Ltd Unit 120 Mill Hill House 6 The Broadway	Addre	ee	5 Hawkshead Road Bromborough	
Contact	Carl Blanckensee	Contact	Tuscola (109) Ltd	Teleph	none	0151 343 1963	
Telephone		Telephone	020 3325 9181	Websi	te	www.kimpton.co.uk	
Mobile	07745 526614	Mobile					
Email	asquithaustin@outlook.com	Email	asquithaustin.ap@outlook.com	Email		helpdesk@kimpton.co.uk	

Asset - Cylinder DHW	V					Date	of Test - 23/11/2022
Make	Model	Location	Serial No.	Barcode Number	Notes	Asset ID	Pass / Fail
Megaflow	1500LH	Boiler Room	•	1		2637	Pass

Test Reading		of leakage and corrosion.		Drain down bottom of vessel until	Yes
Inspect visible seams and bosses of		Inspect insulation for any deterioration.	Yes	water runs clear.	Tes
cylinder for any signs of leakage and corrosion.	Yes	Examine and check correct operation of safety valves, auto air vents, gauges	Yes		
Check connection pipework for signs	Yes	and valves etc			

							of Test - 23/11/2022
Make	Model	Location	Serial No.	Barcode Number	Notes	Asset ID	Pass / Fail
Megaflow	1500LH	Boiler Room		3		2638	Pass

Test Reading		corrosion.		Inspect insulation for any deterioration.	Yes
Inspect visible seams and bosses of cylinder for any signs of leakage and	Yes	Check connection pipework for signs of leakage and corrosion.	Yes	Examine and check correct operation of safety valves, auto air vents, gauges	Yes





and valves etc	Drain down bottom of vessel until	Yes	water runs clear.	

Comments

Asset - Cylinder DHW Date of Tes							
Make	Model	Location	Serial No.	Barcode Number	Notes	Asset ID	Pass / Fail
Magaflow	1500LH	Boiler Room	LSS151600002AN	3		2639	Pass

Test Reading		of leakage and corrosion.		Drain down bottom of vessel until	Yes
Inspect visible seams and bosses of		Inspect insulation for any deterioration.	Yes	water runs clear.	165
cylinder for any signs of leakage and	Yes	Examine and check correct operation			
corrosion.		of safety valves, auto air vents, gauges	Yes		
Check connection pipework for signs	Yes	and valves etc			

Asset - Boiler Medium	Asset - Boiler Medium Date of Test - 23/11/2022								
Make	Model	Location	Serial Number	Burner Manufacture (if different)	Type of flue/chimney	Asset ID	Pass / Fail		
Potterton Commercial	Sirus WH110	Boiler Room				2641	Pass		

Test Reading		Air/gas ratio control setting High fire	Na	Carbon Monoxide (CO) % Low fire	6
Carry out service to boiler	Yes	Ambient room temperature	18	Carbon Monoxide (CO) % High fire	94
Age approximately	8	Flue gas temp (DegC) Low fire	50.5	Carbon Dioxide (CO2) Low fire	9.2
Heat input rating (kw) Low fire	11.7	Flue gas temp (DegC) High fire	71.0	Carbon Dioxide (CO2) High fire	8.9
Heat input rating (kw) High fire	110.2	Flue gas temp net (DegC) Low fire	31.4	NOX % Low fire	Na
Gas burner pressure Low fire	Na	Flue gas temp net (DegC) High fire	51.9	NOX % High fire	Na
Gas burner pressure High fire	Na	Flue draught pressure (mbar) Low fire	Na	Excess air % Low fire	28.2
Gas rate (m3/hr) Low fire	Na	Flue draught pressure (mbar) High fire	Na	Excess air % High fire	33.9
Gas rate (m3/hr) High fire	Na	Oxygen (o2) % Low fire	4.6	CO/CO2 - Ration Low fire	0.0001
Air/gas ratio control setting Low fire	Na	Oxygen (o2) % High fire	5.3	CO/CO2 - Ration High fire	0.0010





Gross efficiency % Low fire Gross efficiency % High fire	88.7 87.6	Air/gas pressure switch operating correctly?	Yes	Has a Warning/ Advice Record been issued	No
CO flue dilution ppm Low fire	Na	Safety devices operating correctly?	Yes	Has the responsible person been	ΝΙΑ
CO flue dilution ppm High fire	Na	Burner lockout time (in seconds)	60	advised	NA
Flue flow test satisfactory?	NA	Temperature and limit thermostat	Yes	Have warning labels been affixed	NA
Spillage test satisfactory?	NA	working correctly?	res		

Comments

Asset - Boiler Medi	um							Date of	Test - 23/11/20
Make	Model	Loc	ation	Serial Number	Burn Manufac differe	ture (if	Type of flue/chimney	Asset ID	Pass / Fail
Potterton	Sirius Two WH110	Boile	r Room	-				2642	Pass
est Reading				draught pressure (mba		Na		tion ppm Low fire	Na
Carry out service to	arry out service to boiler Yes		Flue	draught pressure (mba	r) High fire	Na	CO flue dilu	tion ppm High fire	Na
Age approximately	e approximately 8		Oxyg	Oxygen (o2) % Low fire		5.2	Flue flow te	Flue flow test satisfactory?	
Heat input rating (k	ing (kw) Low fire 11.7		Oxyg	Oxygen (o2) % High fire		5.5	Spillage tes	Spillage test satisfactory?	
Heat input rating (k	eat input rating (kw) High fire 110.2		Carbo	Carbon Monoxide (CO) % Low fire		24	Air/gas pres	Air/gas pressure switch operating	
Gas burner pressur	re Low fire	Na	Carbo	on Monoxide (CO) % H	ligh fire	83	correctly?		Yes
Gas burner pressur		Na		on Dioxide (CO2) Low		8.9	Safety device	es operating correctly?	Yes
Gas rate (m3/hr) Lo		Na		on Dioxide (CO2) High		8.7	Burner lock	out time (in seconds)	60
Gas rate (m3/hr) Hi		Na		% Low fire		Na		e and limit thermostat	Vaa
Air/gas ratio control		Na	NOX	% High fire		Na	working cor		Yes
Air/gas ratio control		Na		ss air % Low fire		33.1	Has a Warn	ing/ Advice Record been	No
Ambient room temp	U	18	Exces	ss air % High fire		35.7	issued	-	INO
Flue gas temp (Dec		51.5		O2 - Ration Low fire		0.0002	Has the res	ponsible person been	NA
Flue gas temp (Deg		60.0		O2 - Ration High fire		0.0009			INA
Flue gas temp net (32.4		s efficiency % Low fire		88.6	Have warning	ng labels been affixed	NA
Flue gas temp net (40.9		s efficiency % High fire		88.1			





Asset - Boiler Mediu	ım								Date of	Test - 23/11/20
Make	Model	Locati	on	Serial Number	Burı Manufac differ	cture (if		Гуре of e/chimney	Asset ID	Pass / Fail
Potterton	Sirius 2 WH110	Boiler R	oom	•					2643	Pass
est Reading			Flue	draught pressure (mba	r) Low fire	Na		CO flue dilut	ion ppm Low fire	Na
Carry out service to I	boiler	Yes	Flue	draught pressure (mba	r) High fire	Na		CO flue dilut	ion ppm High fire	Na
Age approximately		8	Oxyg	en (o2) % Low fire		5.0		Flue flow tes	t satisfactory?	NA
Heat input rating (kw	 Low fire 	11.7	Oxyg	en (o2) % High fire		5.5		Spillage test	satisfactory?	NA
Heat input rating (kw	/) High fire	110.2	Carbo	on Monoxide (CO) % L	ow fire	6		Air/gas pressure switch operating		Vaa
Gas burner pressure	e Low fire	Na	Carbo	on Monoxide (CO) % H	igh fire	84		correctly?		Yes
Gas burner pressure	e High fire	Na	Carbo	on Dioxide (CO2) Low I	ire	9.0		Safety devic	es operating correctly?	Yes
Gas rate (m3/hr) Lov	v fire	Na	Carbo	on Dioxide (CO2) High	fire	8.9		Burner locko	ut time (in seconds)	60
Gas rate (m3/hr) Hig	h fire	Na	NOX	% Low fire		Na		Temperature	and limit thermostat	Yes
Air/gas ratio control		Na	NOX	% High fire		Na		working corr	ectly?	res
Air/gas ratio control		Na		ss air % Low fire		31.4		Has a Warni	ng/ Advice Record been	No
Ambient room tempe		18	Exces	ss air % High fire		35.7		issued	-	INO
Flue gas temp (Deg		48.5		O2 - Ration Low fire		0.0001	1	Has the resp	onsible person been	NA
Flue gas temp (Deg		74.5	CO/C	O2 - Ration High fire		0.0009)	advised		INA
Flue gas temp net (D		23.6		s efficiency % Low fire		89.0		Have warnin	g labels been affixed	NA
Flue gas temp net (D		49.1		s efficiency % High fire		87.7				

Asset - Expansion V	essel Medium					Date	of Test - 23/11/2022
Make	Model	Location	Serial Number	Volume	Barcode Number	Asset ID	Pass / Fail
Lowara		Boiler Room	233442			2646	Pass

Test Reading		Visually check for corrosion and leaks.	Yes	necessary.	
Where practical flush through and purge to drain.	í es	With the vessel empty, check cushion pressure and record, top up if	Yes		





Comments

Asset - Water Booste	er Set					Date	of Test - 23/11/2022
Make	Model	Location	Serial No.	Label No.	Notes	Asset ID	Pass / Fail
	3 Pump	No.1 - Boiler Room	•			2647	Pass

Test Reading

Comments

Asset - Non Domestic Boiler Room Date of Test - 2					of Test - 23/11/2022	
Boiler Room Location					Asset ID	Pass / Fail
Boiler Room					3508	Pass

Test Reading		(cm2)		Is ventilation satisfactory	Yes
Flue/chimney system installed in accordance with appropriate standards	Yes	Natural Low level ventilation free area(cm2)	800cm	Gas booster(s)/compressor(s) operating correctly	Na
Fan flue interlock operating correctly Appliance serviced	NA Yes	Mechanical ventilation inlet flow rate (m3/s)	Na	Has a Warning/ Advice Record been issued	No
Gas installation pipework adequately supported/identified	Yes	Mechanical ventilation outlet flow rate(m3/s)	Na	Has the responsible person been advised	No
Gas installation pipework	Vaa	Mechanical ventilation interlock fitted	No	Have warning labels been affixed	NA
sleeved/labelled as necessary	Yes	Mechanical ventilation interlock	NA		
Natural High level ventilation free area	800cm	operating correctly	INA		





Asset - Non Domestic Gas Pipework	Date	of Test - 23/11/2022
Gas Meter Location	Asset ID	Pass / Fail
	3509	Pass

Test Reading		Actual leak rate m3/hr or mbar	0	Tightness Test Result	Pass
Gas Type	NG	Actual pressure drop mbar	0.2	Has a Warning/ Advice Record been	No
Meter Type	Diaphragm	Visual inspection of pipework,	Pass	issued	INU
Testing Too	IGE/UP/1A	condition	FdSS	Has the responsible person been	NA
Let by test period existing installations	n	Gas pipework installation adequately	Yes	advised	INA
(minutes)	2	supported and identified	165	Have warning labels been affixed	NA
Stabilisation period (minutes)	4	Gas pipework suitably sleeved when	Yes		
Tightness test duration	4	required	163		
Any inadequately ventilated areas	No	Gas pipe correctly sized	Yes		

Comments

Asset - Water Tank						Date	of Test - 23/11/2022
Make	Model	Location	Size	Label No.	Notes	Asset ID	Pass / Fail
Decca Plastic Ltd	GRP	Boiler Room				3510	Pass

Test Reading

Asset - Circulation Pump Date of Test - 23/11/2							
Make	Model	Location	Description VT, CT Etc	Serial Number	Bar code number	Asset ID	Pass / Fail
Ffalflu		Boiler Room	HWS Return Single			3512	Pass

Test Reading		Examine non-return valve heads for		Examine the adjacent pipe work	Voc
Carry out visual inspection	Yes	signs of leakage or corrosion.	Yes	connections for leaks or corrosion.	res





Take pressure and temperature gauge readingsand record where fitted.	Yes	grilles. Inspect all drive belts for signs of	Na	pump and leave the suction valve open to avoid damage to the pump in
Check all pump controls, including the emergency stop push button.	Yes	stretching and cracking. Change over the pump duty at the end	ING	thye event of inadvertent operation.
Check and record inverter set point and amps. Clean inverter ventilation	Yes	of any maintenance operation. Valve off the discharge valve of the standby	Yes	

Comments

Asset - Circulation P	ump					Date	of Test - 23/11/2022
Make	Model	Location	Description VT, CT Etc	Serial Number	Bar code number	Asset ID	Pass / Fail
DAB	Evoplus	Boiler Room	Twin Heating	•		3513	Pass

Test Reading		Check and record inverter set point		thye event of inadvertent operation.	
Carry out visual inspection	Yes	and amps. Clean inverter ventilation	Yes	Examine and test all valves for full and	
Examine non-return valve heads for	Vaa	grilles.		free travel, checking for leaks.	Yes
signs of leakage or corrosion.	Yes	Inspect all drive belts for signs of stretching and cracking.	Na	Lubricate, adjust as required.	
Examine the adjacent pipe work	Vaa			Check electrical connections	Yes
connections for leaks or corrosion.		Change over the pump duty at the end		associated with the unit.	165
Take pressure and temperature gauge	Vaa	of any maintenance operation. Valve off the discharge valve of the standby	Yes	Take ammeter readings of motor.	Yes
readingsand record where fitted.	Yes			Check pump seals for leaks	Yes
Check all pump controls, including the	Yes	pump and leave the suction valve			
emergency stop push button.	168	open to avoid damage to the pump in			

Comments

Remedial Action Taken or Required Scheduled service and gas safety inspection completed. Gas pressures and emissions checked and adjusted were necessary. Condensate trap and electrodes removed inspected and cleaned. Main heat exchanger de-scaled.





Flue integrity checked and ok. Safety device checked and ok. Found 10 inch flue leaking from joint and a new O ring or section of flue is required (I was unable to find any data on flue) Spark generator perished on boiler 3 and needs replacing. Condensate pipe work on boiler 2 perished and needs replacing (2 x 90, 1 x45, 1 coupler and a section of 22mm overflow pipe required). See photos.





Engineer Sign-Off:		Received By:		
THE ABOVE TEST READINGS SATISFY GAS SAFE "GSR NDINSP PAD 6"		Name:	Carl Blanckensee	
Engineer:	Phil Hopper			





Signature:	PZP	Signature:	
------------	-----	------------	--